





# Assembly Instructions

**CTR46** Round Conference Table



- 1.** Lay bottom cleat (BR) on floor. Beginning at start line in bottom cleat (notch in center), wrap flexible shells (SH) tightly around bottom cleat. Velcro ring inside top of flexible shells to complete base.
- 2.** Lay top (T) halves on floor. Slide together, and secure clips.
- 3.** Position top on base to complete unit.

